



Main

Accessory / separate part destination	Ultrasonic sensor
Product compatibility	XXS ultrasonic sensors XXA ultrasonic sensors
Accessory / separate part category	Configuration accessories
Accessory / separate part type	Configuration software

Complementary

Material	Plastic and metal
----------	-------------------

Environment

Ambient air temperature for storage	-20...45 °C
Ambient air temperature for operation	0...45 °C
Relative humidity	95 % without condensation

Packing Units

Unit Type of Package 1	PCE
Number of Units in Package 1	1
Package 1 Weight	1.2 kg
Package 1 Height	13 cm
Package 1 width	30 cm
Package 1 Length	40 cm